



Adjustment of 55°-90° crossing using trolley wire



!!! Important

The specified length must always be maintained!!!

The parallel alignment must be maintained!!!



Esko spol. s r.o.

Praha 5, Jinonická 80, 15800 CZ

Email: info@esko-praha.cz

Phone: +420257290280

IČO: 60471999

DIČ: CZ60471999

ADJUSTMENT OF CROSSING 2002.55-90

Publisher:

ESKO spol. s.r.o.

Praha 5, Jinonická 80, 15800 CZ

Email: info@esko-praha.cz

Phone: +420257290280

Author: Ing. Jan Fridrich

Email: support@esko-praha.cz

Issue: January 2026

Version: 001.0EN